



FLOOR CARE TIPS-

1. Maintain proper humidity. Ideal relative humidity is 35-45%.
2. Vacuum or sweep floors as necessary. Sand and grit will wear away the finish.
3. Use felt protectors on furniture legs.
4. Wipe away spills immediately.
5. Use walk-off mats outside entrance doors to catch dirt and use rugs in high traffic areas to lessen wear on the floor finish.
6. Check traffic areas for wear and have your hardwood floors re-coated every 4-6 years.
7. When cleaning your floor, use a damp mop, do not saturate.
8. Keep high heels in good repair to reduce indentations.
9. Do not use wax, oil soaps, dusting sprays, or other household cleaners on polyurethane finished wood flooring. Use only recommended cleaning products.